




*GOWT29 GSWT19 Maintenance



* Customers can put some grease on pivot points (red circle place), with brass or gunmetal bushings.





* Let's maintain your machine!

零件代碼	品名及圖案	用量	備註
20GOWT-A 烤亮銀漆		2SET	1.組立螺絲M10X16L +M10墊圈各2PCS 2.組立LOGO貼紙9440-229 =2PCS (注意方向、居中) 3.貼"廠址"貼紙(美國軍用此處 其他國家不貼) (1)Ø50X1.8X500L
20GOWT-B 烤亮銀漆		1SET	1.組立螺絲M10X20L +M10x4T 螺帽各3PCS 2.組立注意貼紙9440-227 =1PCS 3.組立注意貼紙9440-228 =1PCS
GOWT-C 烤深灰漆		3SET	(5)Ø48x2.0x450L
23GOWT	附件包	1SET	
KGOWT	說明書	1SET	

GOWT ASSEMBLY INSTRUCTIONS


PARTS & HARDWARE ILLUSTRATIONS


A1. M10x16L HEX HEAD BOLT	_____	[4PCS]
A2. M10x20L HEX HEAD BOLT	_____	[3PCS]
B2. M10x4T LOCK NUT	_____	[3PCS]
C1. M10 (I.D) WASHER	_____	[4PCS]
D1. 50x50 FOOT CAP (9211-024)	_____	[4PCS]
D2. 50x75 END CAP (9211-084)	_____	[1PCS]
D3. Ø50 ROUND END CAP (9211-019)	_____	[6PCS]



GOWT ASSEMBLY INSTRUCTIONS

ASSEMBLY





GSRT ASSEMBLY INSTRUCTION

PARTS & HARDWARE ILLUSTRATIONS

- | | | | |
|-----|------------------------------|-------|--------|
| A1. | M10X16L HEX HEAD BOLT | ----- | [4PCS] |
| C1. | M10 (I.D) WASHER | ----- | [4PCS] |
| D1. | 2"X2" FOOT CAP (9211-024) | ----- | [4PCS] |
| D2. | 2"X2" END CAP (9211-087) | ----- | [1PCS] |
| D3. | ø1" ROUND END CAP (9211-016) | ----- | [6PCS] |

A1.



D1.



A [2PCS]

C1.



D2.





B [1PCS]

D3.




C [3PCS]



GSWT ASSEMBLY INSTRUCTIONS

ASSEMBLY



*Well done!

