*MCD2100 Maintenance









* Customers can put some grease on pivot points(red circle place), with brass or gunmetal bushings.







* Let's maintain your machine!


零件代碼	品 名 及 圖 案	用量	備 註
20MCD2100-B2 主架 國麗3124S-閃銀 國麗KL0002透明漆 二塗二烤		1SET	1.組立M6X12L=6PCS 錐形內六角螺絲 2.組立M6 拉帽=4PCS (身體有花) 3.貼9440-316認證貼紙=1PCS
8370-050 壓花板 國邦790-49153F1HT-深灰		1PCS	
20MCD2100-C2 輔助導桿座 國麗3124S-閃銀 國麗KL0002透明漆 二塗二烤		1SET	1.組立8510-062=8PCS 線徑軸承(LMES25UU) 2.組立R40扣環=8PCS 設變單號 2015100003



零件代碼	品名及圖案	用量	備註
20MCD2100-D1 踏板架 國麗3124S-閃銀 國麗KL0002透明漆 二塗二烤		1SET	1.組立650-(6-4)拉釘=12PCS 2.貼9440-055貼紙=1PCS 3.貼工單貼紙=1PCS
8370-039 壓花板 國邦790-49153F1HT-深灰		2PCS	設變單號 2012040012
8370-049 壓花板 國邦790-49153F1HT-深灰		1PCS	
20MCD2100-E 後支撐架 國麗3124S-閃銀 國麗KL0002透明漆 二塗二烤		1PCS	






零件代碼	品 名 及 圖 案	用量	備 註
20MCD2100-G1	踏板架 國麗3124S-閃銀 國麗KL0002透明漆 二塗二烤 	2SET	HLMCD2100內箱
20MCD2100-H1	右扶手 國麗3124S-閃銀 國麗KL0002透明漆 二塗二烤 	1SET	1.組立9162-131=1PCS 浸漬把手Ø24X5tX265L 2.組立9162-127=1PCS 浸漬把手Ø24X5tX192L
20MCD2100-I1	左扶手 國麗3124S-閃銀 國麗KL0002透明漆 二塗二烤 	1SET	1.組立9162-131=1PCS 浸漬把手Ø24X5tX265L 2.組立9162-127=1PCS 浸漬把手Ø24X5tX192L 設變單號 2013010002





零件代碼	品 名 及 圖 案	用量	備 註
23MCD2100	附件包	1PCS	HLMCD2100內箱
25MCD2100	皮帶輪包	1SET	HLMCD2100內箱
FMCD2100	鋼索包	1SET	HLMCD2100內箱
KMCD2100	說明書	1SET	HLMCD2100內箱
GMCD2100	螺絲包	1SET	HLMCD2100內箱
9420-116	MCD2100動作圖銘板	1PCS	9630-126氣泡袋X1 160X460XB-平口
	設變單號 2013100009 事務通知單 2013100004		9180-001保麗龍=6PCS 150X100X50mm 9180-002保麗龍=2PCS 165X130X110mm 9180-009保麗龍=1PCS 150X80X80(無缺口) 9630-177 蜂巢紙=3PCS 138HX35X35 9630-185 蜂巢紙=1PCS 95HX45X30 9630-206 蜂巢紙=2PCS 65HX90X35 9630-213 蜂巢紙=2PCS 35HX60X35 9180-027特固龍=12PCS Ø65X45X215L 9630-009束帶=20PCS 7.5X2TX540L





零件代碼	品 名 及 圖 案	用量	備 註
20MCD2100-J1	輔助踏板 國噴3124S-閃銀 國噴KL0002透明漆 二塗二烤	1SET	1.組立8520-001鋼套=2PCS 2.組立9310-018=1PCS 3/8"阻擋墊 3.組立650-(6-4)拉鉚=6PCS
8370-039	壓花板 國邦790-49153F1HT-深灰	1PCS	





零件代碼	品 名 及 圖 案	用量	備 註
20MCD2100-A2	門框 國麗3124S-閃銀 國麗KL0002透明漆 二塗二烤 	1SET	1.組立M6X12L 半圓頭內六角螺絲=2PCS 2.組立M6華司Ø13=2PCS 3.組立1/2"X1"L 一般外六角螺絲=8PCS 4.組立1/2"華司Ø34=14PCS 5.組立1/2"X1-1/4"L 一般外六角螺絲=6PCS 6.組立M10X25L=4PCS 錐形平頭內六角螺絲 7.組立M6拉帽=12PCS 8.組立M10X12L 圓頭內六角螺絲-CAP=4PCS 9.組立M4X12L 半圓頭十字螺絲=2PCS
8313-144	固定片 國麗3124S-閃銀 國麗KL0002透明漆 二塗二烤 	2PCS	

零件代碼	品 名 及 圖 案	用量	備 註
9220-016	護網 壓克力護網 透明黑 	1PCS	
9220-027	護網 壓克力護網 透明黑 	1SET	1.貼9440-117防夾手貼紙=1PCS
9220-023	護網 壓克力護網 透明黑 	1PCS	
8280-042	導桿 電鍍 	2PCS	設變單號 2015040004 Ø3/4"X1433L
9211-148	上蓋 文字向上 		1.貼9441-370=2PCS 鋁標(Steelfiex) H9211148內箱

零件代碼	品 名 及 圖 案	用量	備 註
8210-176A	10孔選擇桿組 電鍍 	1SET	Ø3/4"X340L
8331-056	L型片 國麗3124S-閃銀 	2SET	1.組立M6X12L=2PCS 半圓頭內六角螺絲 2.組立M6華司Ø13=2PCS
8331-057	L型片 國麗3124S-閃銀 	4SET	1.組立M6X12L=4PCS 半圓頭內六角螺絲 2.組立M6華司Ø13=4PCS
8400-033	選擇上片 	1SET	設變單號 2015040004
	選擇上片		

零件代碼	品 名 及 圖 案	用量	備 註
8280-046	導桿 鍍硬鉻 	2SET	1.組立M10X35L=4PCS 錐形內六角螺絲 Ø25X1235L
8312-077	固定片 國麗3124S-閃銀 	1PCS	設變單號 2017030005
8312-078	固定片 國麗3124S-閃銀 	1PCS	
8331-017	固定片 國麗3124S-閃銀 	1PCS	
23MDCUP	附件包-CUP	1SET	
			9180-002 蜂巢紙=6PCS 9180-025特固龍=8PCS 9180-027特固龍=7PCS 9630-009束帶=8PCS

零件代碼	品 名 及 圖 案	用量	備 註
20MCD2100-F 雙槓(右) 國麗3124S-閃銀 國麗KL0002透明漆 二塗二烤		1SET	1.組立8130-305束子=1PCS Ø38XØ31X15L 2.組立9162-130=1PCS 浸漬把手Ø29X4tX195L 3.組立8890-077鐵套=1PCS Ø38X31X19L 4.5/16"X3/4"L=1PCS 圓頭內六角螺絲-CAP 5.3/16"X3/16"L沉頭螺絲=4PCS 6.9440-053(R)貼紙=1PCS
20MCD2100-K 扶手架 國麗790-49153F1HT-深灰			
20MCD2100-L 雙槓(左) 國麗3124S-閃銀 國麗KL0002透明漆 二塗二烤		1SET	1.組立8130-305束子=1PCS Ø38XØ31X15L 2.組立9162-130=1PCS 浸漬把手Ø29X4tX195L 3.組立8890-077鐵套=1PCS Ø38X31X19L 4.5/16"X3/4"L=1PCS 圓頭內六角螺絲-CAP 5.3/16"X3/16"L沉頭螺絲=4PCS 6.9440-054(L)貼紙=1PCS
20MCD2100-K 扶手架 國麗790-49153F1HT-深灰			

MCD2100 ASSEMBLY INSTRUCTIONS

HARDWARE ILLUSTRATION

D1.Ø50 CAP COVER(8130-131)----[4PCS]
D2.Ø76 END CAP(9211-076)----[2PCS]
D3.Ø3/4" SHAFT COLLAR(9211-147)----[2PCS]
D4.50X150L END CAP(9211-162)----[6PCS]
D5.Ø63.5xØ26x12.7t RUBBER COUNT(9310-011)----[4PCS]
D6.Ø55XØ19.5X32L RUBBER COUNT(9310-027)----[2PCS]
D7.108X15tX263L RUBBER PAD(9310-075)----[4PCS]
D8.Ø110X22L PULLEY(9213-002C)----[1PCS]
D10.WEIGHT SELECTOR BAR(8210-176A)----[1PCS]
D11.STEEL CABLE 2300mm(FMCD2100)----[1PCS]
D12.STEEL BUSHING (8110-127)----[2PCS]
D13.TOP PLATE(8400-033)----[1PCS]

D1. 

D2. 

D3. 

D4. 

D5. 

D6. 


D7. 

D8. 

D10. 

D11. 


D12. 

D13. 

MCD2100 ASSEMBLY INSTRUCTIONS

PARTS ILLUSTRATION SHEET


A1[1SET]
20MCD2100-A2



B2 [1SET]
20MCD2100-B2



C [1SET]
20MCD2100-C2



D1 [1SET]
20MCD2100-D1



E [1SET]
20MCD2100-E



F [1SET]
20MCD2100-F



G1 [2SET]
20MCD2100-G1



H1 [1SET]
20MCD2100-H1




I1 [1SET]
20MCD2100-I1



J[1SET]
20MCD2100-J1




L [1SET]
20MCD2100-L



MCD2100 ASSEMBLY INSTRUCTIONS

PARTS ILLUSTRATION SHEET

M1 [2PCS]
8280-046
Ø25X1235L



N1 [2PCS]
8280-042
Ø3/4"X1433L



O [1PCS]
9220-016



P [1PCS]
9220-027



Q [1PCS]
9220-023




R [1SET]
9211-148



S [2SET]
8331-056



T[4SET]
8331-057




U[1PCS]
8370-049




V[1PCS]
8331-017



W[1PCS]
8312-077




X[1PCS]
8312-078



Y[2PCS]
8313-144




Z [1PCS]
9420-116
EXERCISE CHART



MCD2100 ASSEMBLY INSTRUCTIONS



Above shows STEP 1 assembled and completed



MCD2100 ASSEMBLY INSTRUCTIONS



Above shows STEP 2 assembled and completed






Figure 1




MCD2100 ASSEMBLY INSTRUCTIONS




Above shows STEP 3 assembled and completed



MCD2100 ASSEMBLY INSTRUCTIONS



Above shows STEP 4 assembled and completed




MCD2100 ASSEMBLY INSTRUCTIONS



Above shows STEP 5 assembled and completed


Note : Insert A10 throuth the hole of the Third electing plate and fix it permanently




MCD2100 ASSEMBLY INSTRUCTIONS




Above shows STEP 6 assembled and completed



MCD2100 ASSEMBLY INSTRUCTIONS



Above shows STEP 7
assembled and completed



*Well done!

