


EXM-2750.8



VERSION 0612


HARDWARE ILLUSTRATION SHEET

PAGE 1


HARDWARE ILLUSTRATION SHEET

This exploded view diagram illustrates the assembly of a mechanical device, likely a portable electronic instrument. The components are organized into five rows and four columns, with each part labeled with a unique identifier (D1 through D40). The parts include structural frames, mounting brackets, a large cylindrical component, a long thin rod, various fasteners (screws, nuts, washers, pins), and electrical connectors. The diagram shows the spatial relationship and assembly sequence of these parts, with some components like D34 and D36 shown as cables with connectors.


A[1PCS]




B[1PCS]




C[1PCS]




D[1PCS]




E1[1PCS]




F[1PCS]




G1[1PCS]




H1[1PCS]




I[1PCS]



J[1PCS]




K[1PCS]



L[1PCS]



M[1PCS]




N[1PCS]




O[1PCS]



P1[1PCS]




Q1[1PCS]




R[1PCS]



S[1PCS]




T[1PCS]




U[2PCS]



V[1PCS]



W[1PCS]




X[2PCS]




Y[2PCS]




AA1[1PCS]




AB1[1PCS]




AC[1PCS]




AD[1PCS]




AE[1PCS]




AF1[1PCS]




AG1[1PCS]




AH[1PCS]




AI[1PCS]







AJ[1PCS]






AK[1PCS]




AL[1PCS]

AN[2PCS]
8312-062AO[1PCS]
8312-091AP[1PCS]
8313-066


AQ[1PCS]

AS[2PCS]
8380-009AT[1PCS]
9122-008AU[1PCS]
9112-001


AX[1PCS]




AY[1PCS]




AV1[2PCS]



AZ[2PCS]




EXM-2750.8




EXM-2750.8

* : NEED TO LOOSEN BOTH ALLEN HEAD BOLT
IN PRDER TO REMOVE SHAFT



EXM-2750.8

* : NEED TO LOOSEN BOTH ALLEN HEAD BOLT
IN PRDR TO REMOVE SHAFT



EXM-2750.8


THERE IS A RISK ASSUMED BY INDIVIDUALS WHO USE THIS TYPE OF EQUIPMENT. TO MINIMIZE RISK, YOU MUST FOLLOW THESE RULES:

1. Inspect equipment before each workout. Check that all nuts, bolts, screws and pop pins are in place and fully tightened. Also, before use, check cables for signs of wear. Replace all worn parts immediately. Never use machine if any parts are damaged or missing. Failure to follow these rules may result in serious injury.
2. Keep clear of the cables and all moving parts when the machine is in use.
3. Always make sure all Snap Links are closed when doing any cable/pulley exercises.
4. Exercise with care. Perform your exercises at a smooth moderate pace; never perform jerky or uncoordinated movements that may cause injury.
5. It is recommended that you should workout with a training partner.
6. Do not allow children or minors to play on or around this equipment.
7. If unsure of proper use of equipment, call your local Body-Solid distributor or the Body-Solid customer service department at 1-800-556-3113.
8. **WARNING:** Consult your physician before starting your exercise program. For your own safety, do not begin any exercise program without proper instruction.


RAL2-11-98

5/16" SPRING WASHER x2

5/16"x3/4" ROUND BOLT x2









EXM-2750.8






EXM-2750.8

D33





EXM-2750.8



EXM-2750.8

D36



M10x16L ROUND BOLT x4

M10 WASHERT x4

ASx2

B3x2

D24x2

D36

A19x2

D24x2

A14x2

EXM-2750.8

