















SSM-350G




VERSION 0805

# SSM-350G HARDWARE ILLUSTRATION SHEET



	Qty.		Qty.
 A1. 1/2"X4" HEX HEAD BOLT -----	[8PCS]	D1. 1/2" BOLT CAP (9212-024) -----	[40PCS]
 A2. 1/2"X2 1/2" HEX HEAD BOLT ----	[12PCS]	D2. ø2 1/2"X19t RUBBER DOUNT(9310-012)----	[4PCS]
 A3. 1/2"X2" HEX HEAD BOLT -----	[2PCS]	D3. ø90X10t RUBBER DOUNT (9310-016)-----	[4PCS]
 A4. 1/2"X1" HEX HEAD BOLT -----	[8PCS]	D4. ø3/4" RUBBER DOUNT (9212-006)-----	[18PCS]
 A5. 3/8"X1" HEX HEAD BOLT -----	[2PCS]	D5. ø50 ROUND END CAP (9211-074) -----	[6PCS]
 B1. 1/2" NYLON LOCK NUT -----	[10PCS]	D6. ø4 1/2 " PULLEY (9213-010)-----	[2PCS]
 B2. 3/8" NYLON LOCK NUT-----	[2PCS]	D7. 75X75 END CAP (9211-007)-----	[4PCS]
 C1. 1/2" ROUND END CAP WASHER ---	[40PCS]	D8. 50X75 FOOT CAP (9211-026)-----	[4PCS]
 C2. 1/2" (I.D)WASHER -----	[12PCS]	D9. 2"X3" RUBBER DOUNT (9212-011)-----	[4PCS]
 C3. 3/8" (I.D)WASHER -----	[4PCS]	D10. 2020mm STEEL CABLE-----	[2PCS]
 C4. 1/2" SPRING WASHER -----	[8PCS]		




A [2PCS]




G [1PCS]

L [2PCS]  
8290-005


B [2PCS]




C [1PCS]




J [1PCS]




D-1 [1PCS]




H [1PCS]





I [1PCS]




K [6PCS]




E-1 [1PCS]

M [2PCS]  
8312-062N [2PCS]  
8312-091

F [2PCS]




# SSM-350G



# SSM-350G

While assembling the smith machine it is very important ,  
that while placing the linear bearing covering the on rod (B).  
You do so as straight as possible.  
Failing to do so may cause damage to the linear bearings.



THERE IS A RISK ASSUMED BY INDIVIDUALS WHO USE THIS TYPE OF EQUIPMENT. TO MINIMIZE RISK, YOU MUST FOLLOW THESE RULES:

1. Inspect equipment before each workout. Check that all nuts, bolts, screws and pop pins are in place and fully tightened. Also, before use, check cables for signs of wear. Replace all worn parts immediately. Never use machine if any parts are damaged or missing. Failure to follow these rules may result in serious injury.
2. Keep clear of the cables and all moving parts when the machine is in use.
3. Always make sure all Snap Links are closed when doing any cable/pulley exercises.
4. Exercise with care. Perform your exercises at a smooth moderate pace; never perform jerky or uncoordinated movements that may cause injury.
5. It is recommended that you should workout with a training partner.
6. Do not allow children or minors to play on or around this equipment.
7. If unsure of proper use of equipment, call your local Body-Solid distributor or the Body-Solid customer service department at 1-800-556-3113.
8. **WARNING:** Consult your physician before starting your exercise program. For your own safety, do not begin any exercise program without proper instruction.

RAL2-11-98