


The Surgeon General
has determined that lack
of physical activity is
detrimental to your health.™

Trademark of United States Fitness Products Council



THERE IS A RISK ASSUMED BY INDIVIDUALS WHO USE THIS TYPE OF EQUIPMENT. TO MINIMIZE RISK, YOU MUST FOLLOW THESE RULES:

1. Inspect equipment before each workout. Check that all nuts, bolts, screws and pop pins are in place and fully tightened. Also, before use, check cylinders for leaking. Replace all worn parts immediately. Never use machine if any parts are damaged or missing. Failure to follow these rules may result in serious injury.
2. Keep clear of the cylinder and all moving parts when the machine is in use.
3. Exercise with care. Perform your exercises at a smooth moderate pace; never perform jerky or uncoordinated movements that may cause injury.
4. It is recommended that you should workout with a training partner.
5. Do not allow children or minors to play on or around this equipment.
6. If unsure of proper use of equipment, call your local distributor.
7. **WARNING:** Consult your physician before starting your exercise program. For your own safety do not begin any exercise program without proper instruction.



CL2CS.1 OWNER'S MANUAL

CL2CS ASSEMBLY INSTRUCTIONS



HARDWARE ILLUSTRATION





(A1)ROUND ALLEN HEAD M8X15L PARTIAL THREAD QTY.10





(A2)ROUND ALLEN HEAD M8X25L PARTIAL THREAD QTY.8





(A3)ROUND ALLEN HEAD M10X16L PARTIAL THREAD QTY.4




(A4)HEX BOLT M10X50L PARTIAL THREAD QTY.2



(A5)HEX BOLT M12X60L PARTIAL THREAD QTY.1




(A6)HEX BOLT M12X115L PARTIAL THREAD QTY.2




CL2CS ASSEMBLY INSTRUCTIONS


HARDWARE ILLUSTRATION



(A7)HEX BOLT M12X140L PARTIAL THREAD QTY.2





(A8)HEX BOLT M10X75L PARTIAL THREAD QTY.1




CL2CS ASSEMBLY INSTRUCTIONS



FRAME HARDWARE ILLUSTRATION FOR CL2DA





(AA1)ROUND ALLEN HEAD 3/8"X2"L PARTIAL THREAD QTY.1





(AA2)ROUND ALLEN HEAD M6X16L PARTIAL THREAD QTY.4




(AA3)HEX BOLT M10X45L PARTIAL THREAD QTY.2




(AA4)HEX BOLT M12X90L PARTIAL THREAD QTY.2



(AA5)HEX BOLT M12X95L PARTIAL THREAD QTY.2




(AA6)ROUND ALLEN HEAD M4X12L PARTIAL THREAD QTY.2




CL2CS ASSEMBLY INSTRUCTIONS


FRAME HARDWARE ILLUSTRATION FOR CL2DA



(AA7)ELASTIC BELT (F920003) QTY.1




(AA8)WEIGHT STACK PIN (8250-128) QTY.1




CL2CS ASSEMBLY INSTRUCTIONS


HARDWARE ILLUSTRATION




(B1) NYLON LOCK NUT M10 QTY.3




(B2) NYLON LOCK NUT M12 QTY.4




(B3) LOCK NUT 1/2"X13 UNC QTY.1




(C1) M8(I.D.) FLAT WASHER Ø16 QTY.8




(C2) M8(I.D.) FLAT WASHER Ø20 QTY.2




(C3) M8(I.D.) FLAT WASHER Ø24 QTY.8




(C4) M10(I.D.) FLAT WASHER Ø27 QTY.10




(C5) M12(I.D.) FLAT WASHER Ø34 QTY.9





(C6) M20(I.D.) FLAT WASHER Ø30 QTY.2



(C7) M8 SPRING WASHER QTY.18



(C8) 1/2" SPRING WASHER QTY.1




CL2CS ASSEMBLY INSTRUCTIONS


HARDWARE ILLUSTRATION

D1.Ø1"x70L STEEL BUSHING (8220-244)	[1PCS]
D2.20X40 END CAP(9211-008)	[4PCS]
D3. 60x50 NYLON BUSHING(9211-033)	[2PCS]
D4.25.4X50.8 END CAP(9211-086)	[1PCS]
D5.PLATE CAP (9211-173)	[4PCS]
D6.Ø60X42H DECK BUFFER(9214-037)	[2PCS]
D7. 58X116X29T RUBBER PAD(9310-057)	[1PCS]
D9.Ø110 PULLEY(9213-002B)	[2PCS]
D10.4900mm STEEL CABLE(FCL2CSA)	[1PCS]
D11.EXERCISE CHART (9420-130)	[1PCS]


D1




D2




D3




D4




D5




D6




D7



D9



D10



D11




CL2CS ASSEMBLY INSTRUCTIONS


FRAME HARDWARE ILLUSTRATION FOR CL2DA

DD1.Ø3/4" SHAFT COLLAR(9211-046)-----	[2PCS]
DD2.50X4TX50L RUBBER PAD(9214-002)-----	[1PCS]
DD3.Ø21/2"XØ19.2X19.4T RUBBER DOUNT(9310-010)-----	[2PCS]
DD4.226X13.5tX161 RUBBER PAD(9310-115)-----	[2PCS]
DD5.Ø110 PULLEY(9213-002B)-----	[2PCS]
DD6.TOP PLATE(8400-006)-----	[1PCS]
DD7.Selector Rod(8210-042)-----	[1PCS]
DD8.BOTTLE BRACKET(8388-025)-----	[1PCS]
DD9.BOTTLE RACK(9260-320)-----	[1PCS]
DD10.BOTTLE(9260-123)-----	[1PCS]


DD1




DD2




DD3




DD4




DD5




DD6




DD7



DD8



DD9




DD10




CL2CS ASSEMBLY INSTRUCTIONS

PARTS ILLUSTRATION SHEET


A[1SET]




B[1SET]




C1[1SET]




D[1SET]




E[1SET]




F[1SET]



G[1SET]




H[1SET]




CL2CS ASSEMBLY INSTRUCTIONS

PARTS ILLUSTRATION SHEET


I1[1PCS]
26CL2CSI1




K[1PCS]
8210-232
Ø12.7X108.5L




L[2PCS]
8210-234
Ø5/8"X156L




M[1PCS]
8210-245
Ø17X172L




N[1PCS]
8220-294
Ø20X266L




O[1PCS]
9211-206




P[2PCS]
10CL2CS-15
20X40X2TX710L




R[1PCS]
9111-102



S[1PCS]
9121-113




T[3PCS]
8312-078




CL2CS ASSEMBLY INSTRUCTIONS

FRAME PARTS ILLUSTRATION SHEET FOR CL2DA


AA[1SET]
6610-040




AB[1SET]
6610-041




AC[1SET]
6610-039




AD[2SET]
6670-005




AE[2SET]
8321-066




AF[2PCS]
8280-013
Ø3/4"X1920L




AG[1SET]
8380-084




AH[1SET]
8380-085




CL2CS ASSEMBLY INSTRUCTIONS




Above shows STEP 1
assembled and completed




CL2CS ASSEMBLY INSTRUCTIONS



Above shows STEP 2
assembled and completed




CL2CS ASSEMBLY INSTRUCTIONS




STEP 2


M12X20L ROUND BOLT X2




Above shows STEP 3
assembled and completed





CL2CS ASSEMBLY INSTRUCTIONS



Above shows STEP 4
assembled and completed




CL2CS ASSEMBLY INSTRUCTIONS




CL2CS ASSEMBLY INSTRUCTIONS


Cable Configuration Diagram





CL2CS ASSEMBLY INSTRUCTIONS




Above shows STEP 6
assembled and completed




CL2CS ASSEMBLY INSTRUCTIONS




CL2CS ASSEMBLY INSTRUCTIONS





Above shows STEP 8
assembled and completed




CL2CS ASSEMBLY INSTRUCTIONS



Above shows STEP 9
assembled and completed



CL2CS ASSEMBLY INSTRUCTIONS



M10X15L SOCKET HEAD CAP SCREW X2

STEP 9

O

AH

M10 WASHER Ø19 X2

M10X15L ROUND BOLT X2

STEP 8

M6 WASHER Ø13 X4

M6X12L ROUND BOLT X4

M10 WASHER Ø19 X2

M10X15L ROUND BOLT X2