


The Surgeon General
has determined that lack
of physical activity is
detrimental to your health.™



Trademark of United States Fitness Products Council

THERE IS A RISK ASSUMED BY INDIVIDUALS WHO USE THIS TYPE OF EQUIPMENT. TO MINIMIZE RISK, YOU MUST FOLLOW THESE RULES:



1. Inspect equipment before each workout. Check that all nuts, bolts, screws and pop pins are in place and fully tightened. Also, before use, check cylinders for leaking. Replace all worn parts immediately. Never use machine if any parts are damaged or missing. Failure to follow these rules may result in serious injury.
2. Keep clear of the cylinder and all moving parts when the machine is in use.
3. Exercise with care. Perform your exercises at a smooth moderate pace; never perform jerky or uncoordinated movements that may cause injury.
4. It is recommended that you should workout with a training partner.
5. Do not allow children or minors to play on or around this equipment.
6. If unsure of proper use of equipment, call your local distributor.
7. **WARNING:** Consult your physician before starting your exercise program. For your own safety do not begin any exercise program without proper instruction.

CL2HL OWNER'S MANUAL



HARDWARE ILLUSTRATION





(A1)HEX BOLT M12X25L PARTIAL THREAD QTY.4





(A2)HEX BOLT M12X75L PARTIAL THREAD QTY.2





(A3)ROUND ALLEN HEAD M10X16L FULL THREAD QTY.2




(A4)ROUND ALLEN HEAD M8X10L FULL THREAD QTY.1





(A5)ROUND ALLEN HEAD M8X25L FULL THREAD QTY.4





(A6)HEX BOLT M10X45L PARTIAL THREAD QTY.2





HARDWARE ILLUSTRATION




(A7)HEX BOLT M10X50L PARTIAL THREAD QTY.3




(A8)HEX BOLT M10X115L PARTIAL THREAD QTY.1





(A9)HEX BOLT M12X60L PARTIAL THREAD QTY.1




HARDWARE ILLUSTRATION





(B1)NYLON LOCK NUT M12 QTY.3




(C3)M10(I.D.)FLAT WASHER Ø20 QTY.2





(B2)1/2"NUT-13UNC QTY.1




(C4)M8 SPRING WASHER QTY.5




(B3)NYLON LOCK NUT M10 QTY.6





(C5)M8(I.D.)FLAT WASHER Ø24 QTY.4




(C1)M12(I.D.)FLAT WASHER Ø25 QTY.5




(C6)1/2" SPRING WASHER QTY.1



(C2)M12(I.D.)FLAT WASHER Ø34 QTY.7



(C7)M10(I.D.)FLAT WASHER Ø27 QTY.10



(C8)M10(I.D.)FLAT WASHER Ø19 QTY.2




mm 0 10 20 30 40 50 60 70 80 90 100 110 120 130 140 150



inch 0 1" 2" 3" 4" 5" 6"

CL2HL ASSEMBLY INSTRUCTIONS



FRAME HARDWARE ILLUSTRATION FOR CL2DA





(AA1)ROUND ALLEN HEAD M6X16L FULL THREAD QTY.4




(AA2)HEX BOLT M12X95L PARTIAL THREAD QTY.2




(AA3)ROUND ALLEN HEAD 3/8"X2"L PARTIAL THREAD QTY.1




(AA4)HEX BOLT M12X90L PARTIAL THREAD QTY.2




(AA5)ROUND ALLEN HEAD M4X12L FULL THREAD QTY.2





FRAME HARDWARE ILLUSTRATION FOR CL2DA




(AA6)ELASTIC BELT F920003 QTY.1



(AA7)10LB PIN (8250-128) QTY.1




(AA8)HEX BOLT M10X45L PARTIAL THREAD QTY.2





CL2HL ASSEMBLY INSTRUCTIONS


FRAME HARDWARE ILLUSTRATION FOR CL2DA





(BB1)NYLON LOCK NUT M12 QTY.4



(CC1)M6(I.D.)FLAT WASHER Ø19 QTY.4




(BB2)1/2"NUT-13UNC QTY.1





(CC2)M12(I.D.)FLAT WASHER Ø34 QTY.8





(BB3)NYLON LOCK NUT M4 QTY.2




(CC3)3/8" SPRING WASHER QTY.1




(BB4)NYLON LOCK NUT M10 QTY.2



(CC4)1/2" SPRING WASHER QTY.1



(CC5)M4(I.D.)FLAT WASHER Ø12 QTY.4



(CC6)M10(I.D.)FLAT WASHER Ø27 QTY.4



mm

0 10 20 30 40 50 60 70 80 90 100 110 120 130 140 150

inch

0 1" 2" 3" 4" 5" 6"

HARDWARE ILLUSTRATION

D1.Ø5/8"X22.5L STEEL BUSHING(8110-011)-----	[2PCS]
D2.Ø36XØ26.5X15L SHAFT COLLAR(8130-024)-----	[2PCS]
D3.Ø1"X70L STEEL BUSHING(8220-244)-----	[1PCS]
D4.Ø10XØ20X19.5L STEEL BUSHING(8530-015)-----	[2PCS]
D5.Ø8 SPRING SNAP LINK(8810-001)-----	[2PCS]
D6.□45 END CAP(9211-004)-----	[1PCS]
D7.45.5X60L NYLON BUSHING(9211-047)-----	[2PCS]
D8.Ø24.7X15L END CAP(9211-077)-----	[2PCS]
D9.PLATE CAP(9211-173)-----	[6PCS]
D10.Ø40XØ19.5X140L SHAFT COLLAR(9211-204)-----	[2PCS]
D11.Ø75X3TXØ26 NYLON WASHER(9214-008)-----	[4PCS]
D13.108X263 RUBBER PAD(9310-075)-----	[1PCS]
D14.Ø110X22L PULLEY(9213-002B)-----	[6PCS]
D15.2725mm STEEL CABLE(FCL2HLA)-----	[1PCS]
D16.4565mm STEEL CABLE(FCL2HLB)-----	[1PCS]


D1



D2



D3




D4




D5



D6



D7




D8



D9




D10



D11




D13




D14



D15



D16




FRAME HARDWARE ILLUSTRATION FOR CL2DA

DD1.3/4" Shaft Collar(9211-046)-----	[2PCS]
DD2.2"x2" Rubber Cane Cap (9214-002)-----	[1PCS]
DD3.Ø2-1/2" RUBBER PAD(9310-010)-----	[2PCS]
DD4.226X13.5tX161 RUBBER PAD(9310-115)-----	[2PCS]
DD5.BOTTLE BRACKET(8388-025)-----	[1PCS]
DD6.BOTTLE RACK(9260-320)-----	[1PCS]
DD7.BOTTLE(9260-123)-----	[1PCS]
DD8.Ø110X22L PULLEY(9213-002B)-----	[2PCS]

DD1



DD2



DD3




DD4



DD5



DD6



DD7




DD8




PARTS ILLUSTRATION SHEET


A[1SET]




B[1SET]




C[1SET]




D[1SET]




E[1SET]




F[1SET]



G[1SET]




H[1PCS]
5325J014-26




PARTS ILLUSTRATION SHEET


I[1PCS]
280251




J[1PCS]
8313-144




K[1PCS]
9121-106




L[2PCS]
9161-077




M[1PCS]
9420-128



N[1PCS]
20LB500E




O[1PCS]
20LB1200J



P[1PCS]
8331-017




Q[1PCS]
9211-205




FRAME PARTS ILLUSTRATION SHEET FOR CL2DA


AA[1SET]
6610-040




AB[1SET]
6610-041




AC[1SET]
6610-039




AD[2SET]
6670-005




AE[2SET]
8321-066




AF[1SET]
8210-042
Ø3/4"X596L




AG[1SET]
8400-006




AH[2PCS]
8280-013
Ø3/4"X1920L





AI[1SET]
8380-084




AJ[1SET]
8380-085




CL2HL ASSEMBLY INSTRUCTIONS




CL2HL ASSEMBLY INSTRUCTIONS



Above shows STEP 2
assembled and completed






STEP 1




*: 5/16"X3/8"L SCREW X10

NEED TO LOOSEN BOTH ALLEN HEAD BOLT
IN ORDEA TO REMOVE SHAFT





CL2HL ASSEMBLY INSTRUCTIONS



Above shows STEP 5
assembled and completed







Figure 1




DETIAL VIEW


CL2HL ASSEMBLY INSTRUCTIONS





*: 5/16"X5/16"L SCREW X2
NEED TO LOOSEN BOTH ALLEN HEAD BOLT
IN ORDEA TO REMOVE SHAFT




Cable Constitute illustration






CL2HL ASSEMBLY INSTRUCTIONS




Cable Constitute illustration




CL2HL ASSEMBLY INSTRUCTIONS



CL2HL ASSEMBLY INSTRUCTIONS



Above shows STEP 9
assembled and completed



CL2HL ASSEMBLY INSTRUCTIONS

