


GOWT



OWNER'S MANUAL

GOWT ASSEMBLY INSTRUCTIONS

PARTS & HARDWARE ILLUSTRATIONS

A1. M10x16L HEX HEAD BOLT	_____	[4PCS]
A2. M10x20L HEX HEAD BOLT	_____	[3PCS]
B2. M10x4T LOCK NUT	_____	[3PCS]
C1. M10 (I.D) WASHER	_____	[4PCS]
D1. 50x50 FOOT CAP (9211-024)	_____	[4PCS]
D2. 50x75 END CAP (9211-084)	_____	[1PCS]
D3. Ø50 ROUND END CAP (9211-019)	_____	[6PCS]

A1



A2




B1



C1



D1




D2




D3





A [2PCS]



B [1PCS]



C [3PCS]



GOWT ASSEMBLY INSTRUCTIONS

ASSEMBLY

