


(A1)ROUND ALLEN HEAD M12X125L PARTIAL THREAD QTY.4



(B1) LOCK NUT M12 QTY.4




(C1)M12(I.D.)FLAT WASHER Ø34 QTY.8





(C2)SPRING WASHER M12 QTY.4

A [1SET]



B [1SET]



#Please tighten the screw after all parts assembled.
or please tighten all screws after all parts joint together

#Suggest the method
of rope winding.

