




*JGHT2400*





Assembly & Instructions

**OWNER'S & MANUAL**



# JGHT2400 HARDWARE

(shown in actual size)



A1.M8X12L Round Head Socket CAP Screw Qty.1(Pre-installed)





A2.M8X25L Hex Head Bolt Qty.8





A3.1/2"X2" Hex Head Bolt Qty.4






A4.M10X25L Taper Flad Head Socket Screw Qty.2



A5.M10X45L Hex Head Bolt Qty.4





A6.M10X50L Hex Head Bolt Qty.3





# JGHT2400 HARDWARE

(shown in actual size)



A7.M12X25L Hex Head Bolt Qty.4





A8.M12X35L Hex Head Bolt Qty.2





A9.M12X80L Hex Head Bolt Qty.5






A10.M12X85L Hex Head Bolt Qty.4



A11.M12X75L Hex Head Bolt Qty.4



A12.M12X130L Hex Head Bolt Qty.1





# JGHT2400 HARDWARE

(shown in actual size)


A13.M4X10L Blind Rivets Qty.12(Pre-installed)




A14.M10X25L Allen Screw Qty.2




C1.M8 Spring Washer Qty.9(1pcs Pre-installed)




C2.M8 Washer (Ø22) Qty.8





C3.1/2" Spring Washer Qty.2



C5.M10 Washer (Ø27) Qty.16




C6.M12 Spring Washer Qty.7




# JGHT2400 HARDWARE

(shown in actual size)


C7.M12 Washer (Ø24) Qty.41




B1. 1/2" Nut (13 tooth) Qty.2





B2. 1/2" Nylon Lock Nut Qty.4



B3. M10 Nylon Lock Nut Qty.7




B4. M12 Nylon Lock Nut Qty.13




# JGHT2400 PARTS


C[1PCS]




L[1PCS]




J[1PCS]




M2PCS]




B[1PCS]




E[1PCS]




K[1PCS]




I[1PCS]




P[1PCS]




O[1PCS]




F[2PCS]  
(8312-062)




G[2PCS]  
(8312-077)




H[1PCS]  
(8313-188)




D[1PCS]




Q[1PCS]  
(8312-013)




N[1PCS]  
(9131-076)




P[1PCS]  
(9121-126)




Z[2PCS]  
(8370-079)



X[1PCS]  
(9630-331)



Y[1PCS]  
(9630-330)



## JGHT2400 PARTS

|                                                   |      |
|---------------------------------------------------|------|
| D1.Belt Pulley(9213-002C).....                    | 7PCS |
| D2.The Round Side Cover(9211-173).....            | 9PCS |
| D3.Belt Pulley(9213-010B).....                    | 4PCS |
| D4.Rubber Blanket(9310-075).....                  | 1PCS |
| D5.Rubber Blanket(9310-134).....                  | 4PCS |
| D6.Double Set Of(9211-033)(Pre-installed).....    | 1PCS |
| D7.Snap Fastener(9211-036)(Pre-installed).....    | 4PCS |
| D8.Adjust Team(8250-066)(Pre-installed).....      | 1PCS |
| D9.Balancing Bumper(9214-037)(Pre-installed)..... | 1PCS |
| D10.3305mm Steel Cable.....                       | 1PCS |
| D11.2910mm Steel Cable.....                       | 1PCS |

D1




D2




D3




D4



D5




D6




D7




D8



D9




D10





D11








Above shows STEP 1  
assembled and completed








Above shows STEP 2  
assembled and completed






Above shows STEP 3  
assembled and completed





Above shows STEP 4  
assembled and completed



# JGHT2400 Exploded View

**KEY**  
Match the letters in each triangle

|    |          |
|----|----------|
| △A | connects |
| △B | connects |
| △C | connects |
| △D | connects |
| △E | connects |
| △F | connects |

PAGE 11