






NMDR2




Assembly & Instructions

OWNER'S & MANUAL


A1. M10x15 Round Head Screw Qty.12




C1. M10 Spring Washer Qty. 12




C2.M10 WASHER(Ø20) Qty.12




A [1PCS]




B [1PCS]



C [1PCS]




D [1PCS]





D1.50x100 RoundEnd Cap (9211-193).....2PCS
D2.Rubber Pad (9310-076).....4PCS

D1



D2





Above shows STEP 1
assembled and completed

