






NDR2.5





Assembly & Instructions

OWNER'S & MANUAL



NDR2.5 HARDWARE
(shown in actual size)





A1.M12X25L Hex Head Bolt Qty. 4




A2. M12X65L Hex Head Bolt Qty. 8





A3. M10X30L Taper Screw Qty.40




B1. M12 Nylon Lock Nut Qty. 8




NDR2.5 HARDWARE
(shown in actual size)




B2. M10 Nylon Lock Nut Qty. 40



C1.M12Washer (Ø34) Qty.4




C2. M12 Bolt Cap Washer Qty. 16




C3.M10 Spring Washer (Ø27) Qty.40

NDR2.5 HARDWARE
(shown in actual size)


A[2PCS]



B[2PCS]



C[1PCS]



D[4PCS]
(8312-168)




NDR2.5 HARDWARE (shown in actual size)

D1. M12 Bolt Cap.....	16PCS
D2.40X80 Round End Cap (9211-192)	2PCS
D3.Rubber Pad(9310-076).....	4PCS
D4.Rubber Pedestal (9310-099).....	20PCS
D5.Rubber Pedestal (9310-098).....	20PCS


D1




D2




D3




D4



D5





Above shows STEP
assembled and completed

